

Fuji plus LCD Parts Out Of One Year Warranty Policy

RMA Service Charge

Please follow the RMA service rules as following:

1. When the 17" or 19" LCD parts out of one year warranty MMITEK will charge customers replaced the new component fee and the shipping fee to the customers.

Here is all replaced new component cost:

1. Inspection fee \$40.00
2. AC Adapter- \$ 35.00
3. Inverter - \$ 65.00 (included with panel)
4. AD Board - \$65.00 (included with panel)
5. Any repairs parts of the unit, the warranty only 30 business days.

2. Fuji Plus LCD warranty explain at following:

Under one year no charge parts and shipping fee.

After one year only charge parts no shipping fee charge.

After three year MMITEK will charge parts &shipping fee and inspection fee.

3. How to work inspection for your LCD Monitor:

Call MMITEK Service Center/ or email rma@mmitek.com

Tell customer rep what is your LCD Monitor problem

Ask customer rep Issue RMA number for you

Put RMA number to your LCD Monitor shipping box (included AC Adapter)

All products must be returned in the their original packaging, MMITEK

Reserves the right to reject any products not returned in their original packaging.

4. The following conditions are excluded from our standard warranty:

The monitor is damaged by wrong/illegal operation, shipping, accident or natural disaster;

The monitor has been fixed or re-equipped by other company's technicians or any unauthorized technicians;

The serial No. has not been changed or eliminated;

For more details and policy please call service center of MMITEK.